

58 FLASH CODE 58

Section	Page
58.1 DESCRIPTION OF FLASH CODE 58	58-3
58.2 SAE J1587 EQUIVALENT CODE FOR FLASH CODE 58	58-3

58.1 DESCRIPTION OF FLASH CODE 58

Flash Code 58 indicates a torque overload.

This code is not covered in this manual. If changes occur, notification will be sent from DDC.

58.2 SAE J1587 EQUIVALENT CODE FOR FLASH CODE 58

The SAE J1587 equivalent code for flash code 58 is p 092/0.

